

LTN87** Series (New Chipset) – Hardware Version post 2021.07.1

Neutral Version [V4.32.110 Build 211029](#)

1. Protocol will show HIKVISION on plug-play or manual connection for LTS cameras.
2. Existing connected cameras also have to be default in order for the notification to work correctly.
3. Virtual Host feature is disabled by default, you have to enable it on the browser by logging into the NVR's ip address.
4. Push notifications Setting on the NVR (notify surveillance center setting) are not being changed from LTS Connect app anymore (Original reported issue).

***Factory Reset recommended after upgrade**

How to identify this model model?

If the SN on the box 2107 (2021 / 07) then use this FW to upgrade

